# **Tubular Handles** • straight, front mounting



## **Product Description**

Tubular handles are used, for example, on machine doors.

## Material

#### Handle

- Zinc die-cast, plastic coated, silver, similar to RAL 9006, matt structure
- Zinc die-cast, plastic coated, black, similar to RAL 9005, matt structure

## Handle shank

- Aluminium, anodised
- Aluminium, plastic coated, similar to RAL 9005 black, matt structure


#### Cap


Plastic, light grey


## More information

Customized design on request.

## **Drawing**







Halder, Inc.

## **Order information**

Dimensions								I	Art. No.		
d <sub>1</sub>	I <sub>1</sub>	а	b <sub>1</sub>	d <sub>2</sub>	h₁	h <sub>2</sub>	l <sub>2</sub>	_			
	±0.25										
	[g]										
silver similar to RAL 9006											
28	200	14	25	M6	50	66	214	320	24321.0700		
28	250	14	25	M6	50	66	264	320	24321.0705		
28	300	14	25	M6	50	66	314	360	24321.0710		
28	350	14	25	M6	50	66	364	400	24321.0715		
28	400	14	25	M6	50	66	414	440	24321.0720		
28	500	14	25	M6	50	66	514	480	24321.0725		
28	600	14	25	M6	50	66	614	500	24321.0730		
black similar to RAL 9005											
28	200	14	25	M6	50	66	214	300	24321.0800		
28	250	14	25	M6	50	66	264	360	24321.0805		
28	300	14	25	M6	50	66	314	360	24321.0810		

Page 1 of 2 Published on: 17.11.2024

www.halderusa.com

Dimensions								I	Art. No.
d₁	I <sub>1</sub>	а	b₁	d <sub>2</sub>	h <sub>1</sub>	h <sub>2</sub>	$I_2$	_	
	±0.25								
[mm]									
28	350	14	25	M6	50	66	364	380	24321.0815
28	400	14	25	M6	50	66	414	440	24321.0820
28	500	14	25	M6	50	66	514	480	24321.0825
28	600	14	25	M6	50	66	614	500	24321.0830

## Compliance

## **RoHS** compliant

Compliant according to Directive 2011/65/EU and Directive 2015/863.

## Does not contain SVHC substances

No SVHC substances with more than 0.1% w/w contained - SVHC list [REACH] as of 27.06.2024.

#### **Does not contain Proposition 65 substances**

No Proposition 65 substances included. https://www.P65Warnings.ca.gov/

## **Free from Conflict Minerals**

This product does not contain any substances designated as "conflict minerals" such as tantalum, tin, gold or tungsten from the Democratic Republic of Congo or adjacent countries.



Halder, Inc.

www.halderusa.com Page 2 of 2

Published on: 17.11.2024